



Dynasty Spas Production Change Bulletin

Date:

04/30/2024

Attention:

All Dealers

Subject:

Equipment access
door fasteners

Bulletin ID #:

00013

Should you have any
Suggestions or questions,
Please contact us.

866-361-3699 ext 241
techsupport@dynastyspas.com

In an effort to continue improving the products we offer, the following change or recommendation has been made.


Spa Models

Affected: All Models

Effective Date: 5/6/2024

Currently the equipment access door is attached using a quarter turn latch assembly.

The equipment access door will now be attached by using screws.



Removal of fasteners



Dynasty Spas Production Change Bulletin

Date:

04/30/2024

Attention:

All Dealers

Subject:

Cabinet mounted
stereo dock

Bulletin ID #:

00014

Should you have any
Suggestions or questions,
Please contact us.

866-361-3699 ext 241
techsupport@dynastyspas.com

In an effort to continue improving the products we offer, the following change or recommendation has been made.

Spa Models

Affected: All Models with stereo option

Effective Date: 5/6/2024

The optional stereo system package currently includes a dock to hold mobile audio devices that is mounted in the cabinet panel next to the equipment access door.

The dock will now be removed from the stereo system package. All other features of the stereo system, such as Bluetooth and FM radio will remain the same.

